



## Top cactus drilling rig hit by tornado company

The original shelter was designed after a tornado hit a Texas location in 2009. Since most of the company's Oklahoma and Texas rigs were in the tornado belt, Cactus believed something ...

One cable broke and the container was dented, but all twelve workers survived without serious injury. [17]: 2[11]: 6 The move to tie down change houses for tornado shelters at Cactus drilling ...

Cactus Drilling Profile and History Cactus Drilling Company, LLC operates as a land drilling contractor in the United States. It operates a fleet of drilling rigs that provide contract drilling ...

At a cost of approximately \$500,000, Cactus anchored its rig change houses to withstand an F5 tornado. On 24 May 2011, Cactus Rig 117, operating near ...

At least three were injured after a tornado hit a natural gas drilling rig in northern Texas on Wednesday evening. At around 5:20 p.m. local time, the tornad...

A BOE contributor sent pictures of Cactus Rig 117, which was destroyed by a tornado on May 24, 2011, near Calumet, Oklahoma. The F5 ...

AboutPressCopyrightContact usCreatorsAdvertiseDevelopersTermsPrivacyPolicy & SafetyHow worksTest new featuresNFL Sunday Ticket&#169; 2025 Google LLC

Rig Fleet Our high-spec, fit-for-purpose rigs are equipped with the technology, capacities and capabilities required to tackle today's most complex drilling ...

Cactus Rig 117 Canadian County, Oklahoma. Tornado Aftermath. Picture courtesy Derrick Brown. Link to Story\* May 24, 2011 Injuries reported ...

A massive tornado flattened Cactus Drilling Company's #117 rig in Canadian County, Oklahoma but a tornado safety system saved the lives of the 11 crew, who weathered ...

The rig itself is laying on it's frontside, turned 180 degrees and looks to be 50 feet or more from the actual well it was on. The "draw-works" (hoist unit) is literally upside down ...

Kenny Baker is the Director of Personnel Development for Cactus Drilling Company, L.L.C., and has 27 years of experience working in the Oil & Gas Industry. Following in his father's ...



## Top cactus drilling rig hit by tornado company

Cactus Drilling remains one of the most active drilling contractors in the U.S., playing a crucial role in oil and gas development across key ...

OverviewTornado summaryMeteorological synopsisImpactsExternal linksThe supercell that eventually generated the El Reno-Piedmont tornado first produced a tornado in Caddo County, Oklahoma, which tracked from west of the town of Lookeba to just northeast of it. The Lookeba tornado developed at 3:31 p.m. and persisted for approximately 16 minutes, traveling nine miles (14 km) and destroying multiple structures. The 800-yard (730 m)-wide tornado earne...

Oklahoma City-based Cactus Drilling Co. LLC credits its reinforced safe room for helping 13 employees and contractors survive a direct ...

Anyways, here"s some absolutely incredible damage photos from the Cactus 117 Oil Rig where the tornado likely hit maximum intensity. This is easily some of the most violent and ...

Cactus Rig 117 Canadian County, Oklahoma. Tornado Aftermath. Picture courtesy Derrick Brown. Link to Story\* May 24, 2011 Injuries reported when storm hits Oklahoma oil rig ...

The issue was the context; to put it bluntly, this was among the most violent tornadoes ever seen in modern times. The feats were numerous, ...

Jul 20, 2021 - Forwarded from one of our service techs: This happened yesterday, 5/24/2011, close to Calumet, OK- Pictures were taken by an SLB employee who was there - An F5 ...

EL RENO -- An El Reno official says 20 workers at an oil and gas rig were hurt when a possible tornado moved through the area. Community ...

Careers Are you interested in becoming part of a team that does challenging and important work while achieving rewarding results? Cactus may well be the career home you"re searching for. ...

Floyd said he didn"t know the extent of the workers" injuries at the rig owned by Cactus Drilling. Emergency workers also contained a gas leak caused by damage to the plant, and damage ...

There, the tornado struck the Cactus 117 oil drilling rig site at EF5 intensity, completely destroying it. When it hit, the rig"s pipes and drill head were inserted deep in the ...

One cable broke and the container was dented, but all twelve workers survived without serious injury. [17]: 2 [11]: 6 The move to tie down change houses for ...

The issue was the context; to put it bluntly, this was among the most violent tornadoes ever seen in modern



## Top cactus drilling rig hit by tornado company

times. The feats were numerous, varied, nearly beyond ...

The origin of Oklahoma City-based Cactus dates back to the 1970s, when it started as Cactus Drilling Corporation, which operated for several years before its assets were ...

A BOE contributor sent pictures of Cactus Rig 117, which was destroyed by a tornado on May 24, 2011, near Calumet, Oklahoma. The F5 tornado was 1/2 mile wide with ...

Contact us for free full report

Web: <https://www.nsprojectsandconstruction.co.za/contact-us/>